

# TEAVE VÄGA OHTLIKE AINETE OHUTU KASUTAMISE KOHTA

## REACH-MÄÄRUSE ARTIKKEL 33 VÄGA OHTLIKE AINETE KOHTA

Hea klient!

REACH-määruse (EÜ nr 1907/2006) artikli 33(1) eesmärk on võimaldada tarnitavate toodete saajatel võtta asjakohaseid riskijuhtimismeetmeid, mis võivad tuleneda toodetes leiduvate, kehtivas autoriseerimisele kuuluvate kandidaatainete loetelus sisalduvate väga ohtlike ainete (VOA) olemasolust, eesmärgiga tagada selliste ainete ohutu kasutamine.

FORD toetab nii REACH-määruse põhieesmärke üldiselt kui ka artikkel 33(1) eesmärke eraldi võetuna, need ühtivad meie püüdlustega edendada meie toodete vastutustundlikku tootmist, käitlemist ja kasutamist.

### VÄGA OHTLIKE AINETE MÄÄRATLEMINE

Meie parima teadmise kohaselt, mis põhineb meie tarneahelast saadud teabel ja meie endi tooteandmetel, on toodete komponentides leiduvad massiosa 0,1% ületavas koguses VOAd esitatud konkreetse sõiduki/osa asjaomases väga ohtlike ainete loetelus.

### Täpne teave väga ohtlikke aineid sisaldavate toodete ohutu kasutamise kohta

Kui on kohaldatav, lisatakse täpne teave väga ohtlikke aineid sisaldavate toodete ohutu kasutamise kohta konkreetse sõiduki/osaga kaasas olevasse asjaomasesse väga ohtlike ainete loetellu.

### Üldine teave toodete ohutu kasutamise kohta

Iga FORDi sõidukiga on kaasas omaniku käsiraamat, kus on toodud sõiduki omanikele/kasutajatele mõeldud teave ohutu kasutamise kohta. FORDi poolt antav teave sõidukite remontimise ja hoolduse ning originaalosa kohta sisaldab ka teeninduspersonalile suunatud teavet ohutu kasutamise kohta.

Kui sõiduki osades leidub VOAsid, on konkreetse sõiduki/osa juurde kuuluvas väga ohtlike ainete loetelus näidatud VOAsid kasutatud selliselt, et nende potentsiaalne kokkupuude klientidega on minimaalne ning oht inimestele ja keskkonnale on välistatud, kui sõidukit ja selle osi kasutatakse ettenähtud viisil ning remont, hooldus ja korrashoid viiakse läbi kooskõlas nende tegevuste tehniliste juhendite ja tööstusharu heade tavadega.

Euroopa Liidu õigusaktide kohaselt tohib kasutuselt kõrvaldatud sõidukit kõrvaldada üksnes tegevusloaga töötlemiskojas. Sõiduki osade kõrvaldamisel tuleb järgida kohapeal kehtivaid õigusakte ja kohalike omavalitsuste juhiseid.

## Mudel: Ford Mustang

ECHA kandidaatainete loetelul põhinev väga ohtlike ainete loetelu  
seisuga 1. juuli 2021

Täpne teave väga ohtlike aineid sisaldavate toodete ohutu kasutamise  
kohta

Täpne teave ohutu kasutamise kohta pole nõutav – järgige üldist teavet toodete  
ohutu kasutamise kohta.

Commodity	REACH SVHCs
A/C Compressor	Lead[7439-92-1]
A/C Condensers and Accumulators	Lead[7439-92-1]
A/C Lines, Receiver Drier and Accumulator	Lead[7439-92-1]
ABS/ESC Module	Imidazolidine-2-thione[96-45-7]
	Lead[7439-92-1]
AC Lines, Receiver Drier and Accumulator	Lead[7439-92-1]
Accessories	C,C'-azodi(formamide)[123-77-3]
	Lead[7439-92-1]
Active and Air Suspension	Lead[7439-92-1]
Adaptive Cruise Control	Lead[7439-92-1]
AIS - Air Cleaner and Low Pressure Ducts	Lead[7439-92-1]
AIS - High Pressure Ducts	Lead[7439-92-1]
Antenna	4,4'-Isopropylidenediphenol[80-05-7]
	Lead[7439-92-1]
Applied Decorative Trim - (IP)	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
	Lead[7439-92-1]
	Silicic acid, lead salt[11120-22-2]
Audio and Navigation Head Units	Imidazolidine-2-thione[96-45-7]
	Lead[7439-92-1]
	Silicic acid, lead salt[11120-22-2]
Axle	Boric acid[10043-35-3]
Back Window	Lead[7439-92-1]
Badging	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
	Lead[7439-92-1]
Battery, Heat Shield & Battery Management System	Lead[7439-92-1]
Beam Rear Axle Assembly	Lead[7439-92-1]
Body And Rear End Wiring	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
Body Control Module	Lead[7439-92-1]
Body Dash and Cowl	C,C'-azodi(formamide)[123-77-3]
Body Side	C,C'-azodi(formamide)[123-77-3]
	Phenol, dimethyl-, phosphate (3:1)[25155-23-1]
Bodyside, Wheel Arch, Rocker Moldings	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
	Tris(nonylphenyl)phosphite[26523-78-4]
Brake - Parking	Lead[7439-92-1]

<b>Brake Actuation</b>	Lead[7439-92-1]
<b>Brake Lines and Hoses</b>	Imidazolidine-2-thione[96-45-7]
	Lead[7439-92-1]
<b>Brake Tubes and Hoses</b>	Lead[7439-92-1]
<b>Brakes - Caliper &amp; Anchor Brkt Assy (Front, Rear)</b>	Lead[7439-92-1]
	Tris(nonylphenyl)phosphite[26523-78-4]
<b>CHMSL</b>	Lead[7439-92-1]
<b>Clutch / DMF (Dual Mass Flywheel)</b>	Lead[7439-92-1]
<b>Control Arm and Bushing Assembly</b>	Imidazolidine-2-thione[96-45-7]
<b>Convertible Top Assembly</b>	Lead[7439-92-1]
<b>Cooling Hoses &amp; Bottles</b>	Lead[7439-92-1]
<b>Driver Information Module (Instrument Cluster)</b>	Boric acid[10043-35-3]
	Lead[7439-92-1]
	Silicic acid, lead salt[11120-22-2]
<b>EDS Wiring Assembly &amp; Components</b>	1-Methyl-2-pyrrolidone[872-50-4]
	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
	Lead[7439-92-1]
<b>Electro/Mechanical Devices</b>	Lead[7439-92-1]
<b>Electronic Climate Control Unit</b>	Lead[7439-92-1]
<b>Electronic Modules - Amplifiers</b>	1,6,7,8,9,14,15,16,17,17,18,18-Dodecachloropentacyclo[12.2.1.16,9.02,13.05,10]octadeca-7,15-diene[13560-89-9]
	Lead[7439-92-1]
<b>Electronic Modules - Headlamp</b>	Lead[7439-92-1]
<b>Electronic Modules - Suspension</b>	Lead[7439-92-1]
<b>Electronic Modules - SYNC</b>	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one[71868-10-5]
	2-Methylimidazole[693-98-1]
	Lead[7439-92-1]
<b>Emission Control Components</b>	Refractory ceramic fibres[142844-00-6]
<b>Engine Covers and Badges</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
<b>Engine Water Pumps</b>	Lead[7439-92-1]
<b>Evaporator and Blower Assembly (HVAC Module)</b>	Lead[7439-92-1]
<b>Exhaust Cold End (Muffler &amp; Output Pipe Assembly)</b>	Lead[7439-92-1]
	Sodium borate, decahydrate[1303-96-4]
<b>Exhaust Hot End (Catalytic Convertor)</b>	Refractory ceramic fibres[142844-00-6]
<b>Exhaust Manifolds</b>	Lead[7439-92-1]
<b>Exterior Cargo Management</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
<b>Exterior Mirrors</b>	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one[71868-10-5]
	4,4'-Isopropylidenediphenol[80-05-7]
	Lead[7439-92-1]
<b>FEAD</b>	Octamethylcyclotetrasiloxane[556-67-2]
<b>First Row Door Window Lift Assy</b>	Lead[7439-92-1]
<b>Front Bumper Skin and Foams</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
<b>Front Caliper, Anchor and Attaching Components</b>	Lead[7439-92-1]

<b>Front Door Trim Panel</b>	Lead[7439-92-1]
<b>Front Seat Frames</b>	Lead[7439-92-1]
<b>Front Side Door Dynamic Weatherstrip</b>	C,C'-azodi(formamide)[123-77-3]
	Imidazolidine-2-thione[96-45-7]
<b>Front Side Doors Glass Runs &amp; Belts</b>	C,C'-azodi(formamide)[123-77-3]
<b>Fuel Canister Assembly</b>	Lead[7439-92-1]
<b>Fuel Filler and Flap</b>	Imidazolidine-2-thione[96-45-7]
<b>Fuel Lines</b>	Lead[7439-92-1]
<b>Fuel Tanks</b>	Lead[7439-92-1]
<b>Generator/Alternator</b>	4,4'-Isopropylidenediphenol[80-05-7]
	Acrylamide[79-06-1]
	Lead[7439-92-1]
<b>Headlamp Cluster</b>	1-Methyl-2-pyrrolidone[872-50-4]
	Lead[7439-92-1]
<b>Headliner Assembly</b>	Lead[7439-92-1]
<b>I/S Mirror</b>	Lead[7439-92-1]
<b>Infotainment Antennas and Cables</b>	Lead[7439-92-1]
<b>Instrument Panel Harness</b>	Lead[7439-92-1]
<b>Instrument Panel Main Molding</b>	C,C'-azodi(formamide)[123-77-3]
	Lead[7439-92-1]
<b>Interior Lighting</b>	Lead[7439-92-1]
<b>IP Finish Panels/Registers</b>	Lead[7439-92-1]
	Silicic acid, lead salt[11120-22-2]
<b>License Plate Lamp</b>	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one[71868-10-5]
<b>Locks</b>	Lead[7439-92-1]
<b>Lower Exterior Finishers</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
<b>Module - Auto or Powershift Trans as Shipped</b>	Lead[7439-92-1]
<b>Module - Front Seat</b>	Diboron-trioxide[1303-86-2]
	Lead[7439-92-1]
<b>Module - Manual or Auto Manual Trans as Shipped</b>	Lead[7439-92-1]
<b>Parking Brake Controls</b>	C,C'-azodi(formamide)[123-77-3]
<b>PCV System</b>	Lead[7439-92-1]
<b>Pedal Box</b>	Lead[7439-92-1]
<b>Pedals</b>	Lead[7439-92-1]
	Octamethylcyclotetrasiloxane[556-67-2]
<b>PEM</b>	Lead[7439-92-1]
<b>Pillar Trim Lower</b>	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one[71868-10-5]
	N,N-Dimethylacetamide[127-19-5]
<b>Pillar Trim Upper</b>	2-Methyl-1-(4-methylthiophenyl)-2-morpholinopropan-1-one[71868-10-5]
<b>Plastic Bumpers and Fascias</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
<b>Powertrain Control Module (PCM/EEC/ ECM)</b>	Lead[7439-92-1]
<b>PT Sensors</b>	Lead[7439-92-1]
<b>Radio Frequency Interference (RFI) Suppression</b>	4-Methylcyclohexyl-1,6-dicarboxylic acid anhydride[19438-60-9]
<b>Rain and Daylight Sensor</b>	Hexahydromethylphthalic-anhydride[25550-51-0]
<b>Rear Closure Finishers</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
<b>Rear Closure Latches</b>	4,4'-Isopropylidenediphenol[80-05-7]

	Octamethylcyclotetrasiloxane[556-67-2]
<b>Rear Quarter Window Assembly (Moveable)</b>	Dibutylbis(pentane-2,4-dionato-O,O')tin[22673-19-4]
<b>Rear Spoiler</b>	C,C'-azodi(formamide)[123-77-3]
<b>Restraint Electronics</b>	Lead[7439-92-1]
<b>Sealing - Door Dynamic Seals</b>	C,C'-azodi(formamide)[123-77-3]
	Imidazolidine-2-thione[96-45-7]
<b>Seat Belts (Front and Rear)</b>	Lead[7439-92-1]
<b>Seats - Structures</b>	Lead[7439-92-1]
<b>Second Row Door, Qtr &amp; Rear Closure Window Lift Assy</b>	Lead[7439-92-1]
<b>Shifter Cables/Brackets - Auto</b>	C,C'-azodi(formamide)[123-77-3]
	Lead[7439-92-1]
<b>Shock Absorbers</b>	1-Propanol, 2,3-dibromo-[96-13-9]
	Lead[7439-92-1]
<b>Side Air Bag (SAB) and Curtain Air Bag (CAB)</b>	Octamethylcyclotetrasiloxane[556-67-2]
<b>Side and Rear Vision (BLIS)</b>	Lead[7439-92-1]
<b>Side Door Latches</b>	Lead[7439-92-1]
<b>Spare Wheel and Tire Assembly</b>	Lead[7439-92-1]
<b>Speakers</b>	1-Methyl-2-pyrrolidone[872-50-4]
<b>Speakers / Tweeters</b>	N,N-Dimethylacetamide[127-19-5]
<b>Starter Motor</b>	Lead[7439-92-1]
	N,N-Dimethylacetamide[127-19-5]
<b>Static Sealing</b>	C,C'-azodi(formamide)[123-77-3]
	Dicyclohexyl-phthalate[84-61-7]
<b>Steering Column</b>	Lead[7439-92-1]
<b>Steering Gear and Linkage</b>	Decamethylcyclopentasiloxane[541-02-6]
	Lead[7439-92-1]
	Octamethylcyclotetrasiloxane[556-67-2]
<b>Steering Wheel, Drive Air Bag</b>	Alkanes, C14-17, chloro[85535-85-9]
	Lead[7439-92-1]
<b>Sun Visors</b>	Boric acid[10043-35-3]
<b>Supplemental Front Lamps</b>	2-(2H-Benzotriazol-2-yl)-4,6-ditertpentylphenol[25973-55-1]
	Lead[7439-92-1]
<b>Suspension Link Components</b>	Lead[7439-92-1]
<b>Switches - General Use</b>	Lead[7439-92-1]
<b>Switches - Headlamp. Window &amp; Door</b>	Lead[7439-92-1]
<b>Switches - Steering Column</b>	Lead[7439-92-1]
<b>Taillamp / Redundant</b>	Lead[7439-92-1]
<b>Temperature Sensors - Climate</b>	Lead[7439-92-1]
<b>TPMS</b>	1,2-Dimethoxyethane[110-71-4]
	Lead[7439-92-1]
<b>Transmission - Auto</b>	Boric acid[10043-35-3]
<b>Transmission - Manual</b>	Lead[7439-92-1]
<b>Transmission (Auto) - Lines/Tubes (Oil Cooler)</b>	C,C'-azodi(formamide)[123-77-3]
	Imidazolidine-2-thione[96-45-7]
<b>Under Engine Closures or Rock Shields</b>	Lead[7439-92-1]
<b>Upper Exterior and Roof Finish</b>	Imidazolidine-2-thione[96-45-7]
<b>Vehicle Lock Set</b>	Lead[7439-92-1]
<b>Wheel</b>	1,2-Dimethoxyethane[110-71-4]

	1,3-Propanesultone[1120-71-4]
	Lead[7439-92-1]
	Tetrahydro-4-methylphthalic anhydride[34090-76-1]
<b>Wiper Assembly (Rear, Front) &amp; Washer System</b>	Lead[7439-92-1]
<b>Wiper Assembly Front</b>	Hexahydromethylphthalic-anhydride[25550-51-0]
	Lead[7439-92-1]